

15-36

Nº 6219

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-6-54 IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_



HOUSE NO. 347

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT 265' 7' DEEP  
CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR Q. Liang

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: \_\_\_\_\_

Nº 6219

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/23 1923

RECEIVED OF A. J. Deana

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Joe Hunt Jr

TO TAP San

SEWER, ON THE W

OF Virginia St

AVE.,

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO. 6955

HOUSE NO. 347

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work i  
walls of building is subject to Massillon Board of Health Regulations.