· 6225

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-27-5	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 87/	<u></u>		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		5 Dee/
WAS LATERAL AT CURB?	o <u>ordid oogida oo ee</u>	e Francisco e e	.
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Bea	vel Cons
SHOW BY DIAGRAM RELATION OF LAT		ERVED.	
		10'	
	er in de servicio de la companio de	5	aup
urgente en la linear de la latte i du me yundisi Rij Linear	ter (kali kali estatutella kali kali kali terbesakan tahun balan kali terbesakan bersakan bersakan bersakan be Bersakan bersakan be	R52/	
		2	
	A CONTRACTOR OF THE PROPERTY O	7.30	
SIGNED INSPECTOR FOR	FILED AT E	GINEER'S OFFICE	
REMARKS:		miidind ko ziiov	

$N_{\odot}^{0} = 6225$

PERMIT TO TAP SEWER

	Massillon, Ohio, July	<u> </u>
RECEIVED OF Jarah Alick		FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED	~	est to profit
FOR WHICH FERMISSION IS GRANTED		
TO TAP SEWER.	ON THE (1)20 +	
OF MILLS MW AVE. TYPE	OF STREET alist	
THE PREMISES BEING LOT NO. 110 F 9		A Company of the Comp
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE		
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	Const	
NAME OF CONTRACTOR	k.	

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.