

Nº 6228

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 2-1-54

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 718

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

51' 5' Deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

R. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Ray L. Thomas
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Nº 6228

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO.

7/28

RECEIVED OF

B Remley

FEE OF \$

2⁰⁰

FOR WHICH PERMISSION IS GRANTED

W. Ekinrode

TO TAP

San.

SEWER, ON THE

E

OF

Taylor St

AVE.
ST.

TYPE OF STREET

Alled

THE PREMISES BEING LOT NO.

4609

HOUSE NO.

718

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.