

11-2

Nº 6230

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 2-24-54 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 325

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 25' 6' deep
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR P. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy L. Thomas
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

Nº 6230

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/28 1924

RECEIVED OF R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED W. Curtis

TO TAP Sanp

SEWER, ON THE W

OF 4th
Chetnut NE

AVE.,
ST.,

TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 662

HOUSE NO. 325

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.