

8-3

Nº 6232

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-10-54 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____



HOUSE NO. 1832

SIZE OF PIPE USED 6" UP DISTANCE FROM FIRST MANHOLE
~~DOWN~~ STREAM TO DITCH AT 40' 6' DE
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No NAME OF CONTRACTOR R. Pernley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Nº 6232

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

7/28

15

RECEIVED OF

R. Remley

FEE OF \$

2⁰⁰

FOR WHICH PERMISSION IS GRANTED

Thomas David

TO TAP

San

SEWER, ON THE

N.

OF

Wickliffe Dr E

AVE.

ST.

TYPE OF STREET

Alcid

THE PREMISES BEING LOT NO.

9076-77

HOUSE NO.

1832

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.