

5-2

Nº 6241

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-14-54 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____



HOUSE NO. 1140

SIZE OF PIPE USED 6" UP DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 45' 5' D & R

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR A. Pernley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6241

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/28

RECEIVED OF

B. Remley

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

E. L. Saunders

TO TAP

San.

SEWER, ON THE

N.

OF

Bluff S.E.

AVE.,
ST.,

TYPE OF STREET

Alled

THE PREMISES BEING LOT NO.

3418

HOUSE NO.

1120

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.