

15-2

Nº 6246

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-14-54

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 833 853

SIZE OF PIPE USED 6"



DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 137' 4' DEEP

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No


NAME OF CONTRACTOR P. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Roy Latham
INSPECTOR FOR CITY



FILES AT ENGINEER'S OFFICE

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 6246

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/29 19

RECEIVED OF

R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

M. Hadak

TO TAP

San

SEWER, ON THE

W

OF

Hemlock

AVE.

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

11087

HOUSE NO.

853

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.