

7-18

Nº 6247

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-3-54

HOUSE NO. 1219

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? NO


WAS ATTACHED TO MAIN YES

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 11' Y" 40' 8.5' DE
110

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

NAME OF CONTRACTOR P Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



up City
M.H.
129' C

SIGNED Poy L. Thomas
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

Nº 6247

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Relay.

MASSILLON, OHIO, 7/31

RECEIVED OF

R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Baptist Temple

TO TAP

San

SEWER, ON THE

SW

OF

Overlook SW

AVE.,

ST.,

TYPE OF STREET

Al. bed

THE PREMISES BEING LOT NO.

of L 288

, HOUSE NO.

1219

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.