


Nº 6294

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-11-54IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 2220SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 138' 8' DEEPWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN NONAME OF CONTRACTOR Pennley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

clay soil

12-1-54

Nº 6294

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/13 1915

RECEIVED OF

R. Remley

FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED

Karl's Russ

TO TAP

San

SEWER, ON THE

N.

OF

Claremont Mt.

AVE.
ST.

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

5996

HOUSE NO.

2216
2220

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.