

Nº 6296

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-11-54

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM "Y" 320' 5' 0" ee

HOUSE NO. 311

SIZE OF PIPE USED 4"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 320' 5'

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Pennley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED A. L. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 12-1-54

REMARKS: Relaid Sandy soil

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 6296
Relay
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/13 1923

RECEIVED OF R. Remley FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED J. J. Ancloux

TO TAP San. SEWER, ON THE S.

OF Ohio St. E. AVE., TYPE OF STREET Hard surface

THE PREMISES BEING LOT NO. 5507, HOUSE NO. 311

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.