

Nº 6297

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-10-54

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 428

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

49' 7' deep

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

Pernley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N. ←



SIGNED

R. L. Luthman
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-1-54

REMARKS:

Pernley

Sandy soil

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 6297

PERMIT TO TAP SEWER

Relay

MASSILLON, OHIO.

11/13

15

RECEIVED OF

R. Remley

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

E. E. Robinson

TO TAP

San

SEWER, ON THE

E

OF

1st. S.E.

AVE.
ST.

TYPE OF STREET

Hard pipe

THE PREMISES BEING LOT NO.

2017

HOUSE NO.

428

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.