

5/31
✓

Nº 6301 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 12-3-54

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 812

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 13'

9' Dec

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR P. P. Remley
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: Clay Soil

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 6301 PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/1/54

RECEIVED OF

Harry Piser

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Robert Eckenrode

TO TAP

Sanitary

SEWER, ON THE

E

OF

17th NE

AVE.,
ST.,

TYPE OF STREET

alled

THE PREMISES BEING LOT NO.

8008

HOUSE NO.

812

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.