FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 2-17-55 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO
 SIZE OF PIPE USED 6 UP DISTANCE FROM FIRST MANHOLE SIZE OF PIPE USED 6 UP STATE MANHOLE CURB LINE AND DEPTH 47/2 UP STATEM M
WAS LATERAL AT CURB? Ve.S
WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR Whom & Princile
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
 Superior of the state of the st
SIGNED DONNAMENT SILED AT ENGINEER'S OFFICE 3-26-55
REMARKS: (2/8 G Y D V P/ S OI) LOWE Y PO L 2 + E Y Z/ TO 7/3 ODE X
16'0FP1Pe

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6313 PERMIT TO TAP SEWER	
Massillon, Ohio.	
RECEIVED OF (Irlan) + Rengley FEE OF S	2
FOR WHICH PERMISSION IS GRANTED Wm Hebke	:
TO TAPSEWER, ON THE	
of Atoner n EAVE. TYPE OF STREET dert	
THE PREMISES BEING LOT NO. 1/195 HOUSE NO. 1840	
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Co	UNC
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	

Note. This permit covers work outside of building

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.