Nº 6314

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 2-26-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 2 75	1 9'Deep
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR	Beaves Const.
		12 iaup
historija (1866) kan niprasistenio System laikuus laikuus laikuus. Nii 1888 – Kanada Laiku Lai	Control Service and appropriate the appropriate control and appropriate and ap	2、 11、 19 11 11 11 11 11 11 11 11 11 11 11 11
SIGNED POY INSPECTOR FOR C	FILED AT ENGINEER'S	OFFICE 6-8-55
REMARKS: U/a	Andre 2 Marie Lander and American Commencer of the Commen	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

DANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COL

i in the second of the second		nn felpene bende blike Listen kijl tika blike		MASSILLON	, Оню, 1	2 33201	15
Re	CEIVED OF	alber	t Can	vei		FEE OF S	<u> </u>
A 25 TO 1		IS GRANTED	the second second		artin	mini sa navangs Til	
TO TAP	Sanit	acy &	SEWE	R. ON THE	W		
of 2	3 200	nw	_AVE., TYP	E OF STREET	du	ji yati wa kweka	
THE PREM	ISES BEING LOT	NO. 108	71.5	<u></u>		333	
				· · · · · · · · · · · · · · · · · · ·			

NAME OF CONTRACTOR Beaver Construction Cv.

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.