

5-29

Nº 6315

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-17-55IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1505SIZE OF PIPE USED 6" upDISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH56' up stream int. 7'0WAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN No



NAME OF CONTRACTOR

P. Penney

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



up stream
MH.



SIGNED

Pop Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

3-26-55

REMARKS:

clay soil

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 6315

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/13 1915RECEIVED OF B. RemleyFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED W. E. SkeneTO TAP SanSEWER, ON THE DistOF Bayview AveAVE., TYPE OF STREET Dist

ST.,

THE PREMISES BEING LOT NO. 8141HOUSE NO. 1505

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.