## Nº 6319

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-25-55	IF SO HOW AND LOCATION FROM THE FIRST MANHOLE DOWN STREAM	3' 10' Dee;
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? NO	of the surface of the first of the contract of the sentence of	108
WAS ATTACHED TO MAIN VEIS	NAME OF CONTRACTOR A	Diana
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.	L,W,W,
	A A A A A A A A A A A A A A A A A A A	1104 3
	The second of th	100 100 q'Dee
		1912
SIGNED Por Lothan	77 FILED AT ENGINEER'S OFFIC	Alley -
REMARKS: Sold	Crour / mail and hearth	3-26-55

## Nº 6319

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio, $\frac{3}{2}\frac{4}{5}$ 19
RECEIVED OF a. J. Diana FEE OF 52.
FOR WHICH PERMISSION IS GRANTED Um. Wut
TO TAP tendary SEWER, ON THE
of Lincoln W AVE. TYPE OF STREET paned
THE PREMISES BEING LOT NO. 197 , HOUSE NO. 131 - Zunco
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR . J. Diana

walls of building is subject to Massillon Board of Health Regulations.

This permit covers work outside of building only. Any work in