FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-25-55	IF SO HOW AND LOCATION FROM TIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 700 WAS ATTACHED TO MAIN 765 SHOW BY DIAGRAM RELATION OF LAT	- NAME OF CONTRACTOR A Diana
and a substitution of the substitution of the second	
Hamiston (amika si titi) di kay <u>indini a</u>	Y or a series of some of the contract of the c
	9'08.
SIGNED POY SIGNED INSPECTOR FOR CO	FILED AT ENGINEER'S OFFICE 3-03-35
REMARKS:	

Nº 6320

PERMIT TO TAP SEWER

:	
 Sometimes of the second second	MASSILLON, OHIO, 3/25/55 15
RECEIVED OF Paul du	n FEE OF S 3.
FOR WHICH PERMISSION IS GRANTED Oak	2 Dim
A .	
7	And the second s
TO TAP Gandary SEW	VER, ON THE
The state of the s	
of 23 rd na extave. T	YPE OF STREET CUL
THE PREMISES BEING LOT NO. Outside	
THE PREMISES BEING LOT NO.	HOUSE NO.
	(
WORK TO BE DONE IN ACCORDANCE WITH ORDINA	NCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
, K · · · ·	THE CIT COUNCI
Rules of the Department of Public Service:	
100 m	
	The state of the s

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.