FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-27-55	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DISTANCE FROM FIRST MANHOLE CURB STREAM TO DITCH AT CURB LINE AND DEPTH CURB LINE AND DEPTH
WAS LATERAL AT CURB? VES	and a figure of the state of the first of the second state of the first of the second state of the second
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR 9 Duning
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
o de la compansión de la Compansión de la compansión	Control of the contro
	and the second of the second o
4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Sand College of College of
	The approximation of the second secon
3 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	il 7 deep
D. J.	/2!
SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
REMARKS: C/2 V So	no for the second space of small about the charge.

N_{2}^{0} 6353

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/26/55 19
RECEIVED OF and FEE OF 58.
FOR WHICH PERMISSION IS GRANTED Clarence Smith
FOR WHICH FERMISSION IS GRANTED
TO TAP LUSILLEY SEWER, ON THE
of 22 nd JE AVE. TYPE OF STREET Ciled
THE PREMISES BEING LOT NO. 4344 , HOUSE NO. 129
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
RULES OF THE DEPARTMENT OF FUBLIC SERVICE.
NAME OF CONTRACTOR . Diana.

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.