

24
21523
Nº 6359

6-40
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-7-55

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Tapped 89' 9' N

HOUSE NO. 822

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH



WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Urban & Ringley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

clay soil

6-31-40

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6359

PERMIT TO TAP SEWER

MASSILLON, OHIO,

6/6

19

RECEIVED OF

Paul Ringley

FEE OF \$

2⁰⁰

FOR WHICH PERMISSION IS GRANTED

same

TO TAP

San

SEWER, ON THE

West

OF

Windsor

AVE.,
ST.,

TYPE OF STREET

Hard surf.

THE PREMISES BEING LOT NO.

10647

HOUSE NO.

822

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Stratford

NAME OF CONTRACTOR

Urban & Ringley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.