


15-21

Nº 6373

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-20-54IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM "Y" 60' 8' deepHOUSE NO. 1404SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____WAS LATERAL AT CURB? NOWAS ATTACHED TO MAIN YesNAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED Roy L. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: clay soil

7-49 2-25 14+

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6373

PERMIT TO TAP SEWER

6/25

MASSILLON, OHIO, 19

RECEIVED OF A. J. Deana FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Victor Beraducci

TO TAP San SEWER, ON THE 77

OF Woodland NE AVE., TYPE OF STREET drbt
ST.,

THE PREMISES BEING LOT NO. Pl 1/4 302, HOUSE NO. 1401

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.