

15-

Nº 6379

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-15-55

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 910

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

127'

6' De



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

Urban & Ringler

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Ray Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: clay soil

8-4-55

Nº 6379

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

July 21st

19

RECEIVED OF

Harry Urban

FEE OF \$13.

FOR WHICH PERMISSION IS GRANTED

Garland Maurer

TO TAP

Sanitary

SEWER, ON THE

~~12th~~ E

OF

Cherry NW

AVE., TYPE OF STREET

Oil

THE PREMISES BEING LOT NO.

Q 83

HOUSE NO.

910

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Urban & Ringley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.