

4-52


NO 6382 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-23-55IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMPlace "Y" in main 204'HOUSE NO. 1119SIZE OF PIPE USED 6'DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHWAS LATERAL AT CURB? NoWAS ATTACHED TO MAIN Yes


NAME OF CONTRACTOR

Kann

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



could not locate Lat.
For this Lot. Went to main
& broke. 3' south was
"Y" it was broke too
Took out broken "Y"
Put in new line from
main to house. cut
off Lat. that "Y" was
broke.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8-4-55

REMARKS:

Gravel soil

Nº 6382

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

7/21

19

RECEIVED OF

Fred Hann

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Michael Petras

TO TAP

San

SEWER, ON THE

W.

OF

13th SE

AVE.
ST.

TYPE OF STREET

Alfred

THE PREMISES BEING LOT NO.

Pl 2270

HOUSE NO.

1119

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Fred Hann

Note: This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.