


8-3-

Nº 6393

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-6-55 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 404
SIZE OF PIPE USED 6" up DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 93' up stream NH. 6'
WAS LATERAL AT CURB? Yes
WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR P. Parnley
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: Clay Soil

8-3

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6393

PERMIT TO TAP SEWER

MASSILLON, OHIO,

8/25

19

RECEIVED OF

C. P. Crowl

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER, ON THE

E

OF

19th NE

AVE., TYPE OF STREET

Hard surf

THE PREMISES BEING LOT NO.

9142-11

HOUSE NO.

404

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.