

Nº 6397

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-7-55 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____



HOUSE NO. 1021

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 93' 9' Deep
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No NAME OF CONTRACTOR Pearley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Prof. Gathorn INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE 93'
10-8-55

REMARKS: clay 50'

Nº 6397

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/9 1920

RECEIVED OF C. A. Rembert

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED same

TO TAP San

SEWER, ON THE W.

OF 17th St.

AVE.,
ST.,

TYPE OF STREET dirt

THE PREMISES BEING LOT NO. of 273

HOUSE NO. 1021

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Rembert

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.