Nº 6431

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-/() -0.5 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	•
	*
HOUSE NO.	
DISTANCE FROM FIRST MANHOLE	. 11
SIZE OF PIPE USED DOWN STREAM TO DITCH AT	10
WAS LATERAL AT CURBY YES	
WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR Penley	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
kirk, bura jalah bura asa saji. Bura bura jakisi sajikisi perakanja ya sajin ngangan jarah bala 🐠 🛣 🛣	
V ← 23→	
P-1-41	1
SIGNED FILED AT ENGINEER'S OFFICE	1_
REMARKS	

Nº 6431

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSIL	LON, OHIO, MONTH	<u> 2</u> ද 19
RECEIVED OF R	around Hom	00.	FEE OF \$ 7 0°6
FOR WHICH PERMISSION IS GRAI			
TO TAP Canitan			
or Oxford n			
THE PREMISES BEING LOT NO			1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
WORK TO BE DONE IN ACCORT			
RULES OF THE DEPARTMENT OF	and the state of t		
NAME OF CONTRACTOR	Remoe		
Note This perm	it covers work outside	of building only.	Any work in

walls of building is subject to Massillon Board of Health Regulations.