Nº 6439

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| | NO LOCATION FROM 34' UP STREAM M. 10' D |
|--|---|
| HOUSE NO. 211 | UO STREAM |
| taga ang ang taga taga ang ang ang ang ang ang ang ang ang | OM FIRST MANHOLE M TO DITCH AT ND DEPTH |
| WAS LATERAL AT CURB? 10 | |
| WAS ATTACHED TO MAIN VES NAME OF CO | ONTRACTOR_ Pinley |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL | |
| | |
| | 0 34' |
| SIGNED ROW Lothern | FILED AT ENGINEER'S OFFICE 12-22-55 |
| / INSPECTOR FOR CITY | |

Nº 6439

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| MASSILLON, OHIO. //- 3 5 - 55 19 |
|--|
| RECEIVED OF RECORD PEE OF 5 2 C |
| FOR WHICH PERMISSION IS GRANTED The Augustican |
| TO TAP A Bandara Sewer on the Month |
| OF CLATA ST. TYPE OF STREET |
| THE PREMISES BEING LOT NO. 93/9 , HOUSE NO. 21/ |
| |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL |
| NAME OF CONTRACTOR Rubble Service. |
| |

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.