Nº _6448

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-1-56	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 101	
SIZE OF PIPE USED 6" U	DISTANCE FROM FIRST MANHOLE CURB LINE AND DEPTH
WAS LATERAL AT CURB7 Y-5	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Vilon & Pringles
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	하다면 하는 마음에 발표하는 사람들이 하는 사람들은 생활을 보는 사람이 되는 것이 되었다. 그림을 받았다는 것으로 보다.
ति विकास करणा विकास विविद्यालया । वृद्यां विकास विकास विकास विकास विकास विविद्यां विकास विविद्यां विकास विकास विविद्यां विकास विविद्यां विकास वि	
	V Otropo
	upt Mt 80eer 12'
SIGNED POY Tather	FILED AT ENGINEER'S OFFICE 3-1-5-6
REMARKS	on the Committee of the Co The Committee of the Committe

Nº 6448

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		Massillon,	Оніо, Д	~ 26	19
RECEIVED OF	Sor The	o Tlou		FEE OF 1	<u> </u>
FOR WHICH PERMISSION					
				j-	
TO TAP	M. A. ST	E. . Type of Street_	m.	0,	
THE PREMISES BEING LO	от но 3 3		HOUSE NO	101	
WORK TO BE DONE IN			3, DULY PASSED	BY THE CITY	Council
Name of Contractor	Walran.	o Renal			

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.