Nº 6457

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-12-56	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 75-6	
SIZE OF PIPE USED 6" WAS LATERAL AT CURB? Yes	CURB LINE AND DEPTH 87 up Stream H . 7'D
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR T. Palone
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.
	70eth 42
	1/p=
P. 41	V 771
SIGNED INSPECTOR FOR	CITY FILED AT ENG NEER'S OFFICE
REMARKS	보다 그 1000년 - 1000년 - 1000년 - 100년 - 100년 1907년 - 100년

Nº 6457

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillo	ом, Оню, Мал	ch 5th 19.
RECEIVED OF	1 Bon		FEE OF \$
FOR WHICH PERMISSION IS GRANTED	萨斯瓦洛曼 化抽烟管 化邻亚烷	ta a a a grégoria de la Califa, a qu	
TO TAP		네마블로 홈트 병장 등장이다.	
or I Thai	AVE. ST. TYPE OF STRE	et oilse	d
THE PREMISES BEING LOT NO.	the state of the s	the contract of the contract o	
WORK TO BE DONE IN ACCORDANCE W	ITH ORDINANCE No. 2	323, DULY PASSED E	Y THE CITY COUNCIL.
NAME OF CONTRACTOR			
Note This permit cover			. Any work in

walls of building is subject to Massillon Board of Health Regulations.