Nº 6482

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-30-56	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 15-17		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH //2'	6'Deep
WAS LATERAL AT CURB? Yes		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	short Ringle
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	0 0
		3'DECP
		ee 40'
	C	0 4
SIGNED Por Latha	172'	>
(INSPECTOR FOR CI	FÎLED AT ENÇÎNEER'S OFF	ICE
		The Control of the Co

Nº 6482

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

			Massillon,	Оню, Сир	i.l 13 th	, 19.
	RECEIVED OF	Chet.	0 K. 100		FEE OF \$, 2 °
	A A Grafia A See A Marin in Fran	RANTED Mas				
				/	<i>t</i> -	
TO TA	Heuper R	MUDINE, AVE	SEWER ON THE		= D/L+	
OF	PREMISES BEING LOT NO	14 of 38	Z		15-17	
WOR	K TO BE DONE IN ACC	ORDANCE WITH OR	DINANCE No. 232	23, DULY PASSEL	D BY THE CITY	COUNCIL
	S OF THE DEPARTMENT		분기를 일 하고 기가 다. 일하고 말 전 하고 있다.			
Nami	e of Contractor	Or Kong				

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.