Nº 6485

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $4-10-56$	IF SO HOW AND LOCATION FROM WYE 22 UP Stream Mt 11
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBY	
WAS ATTACHED TO MAIN_ XC5	NAME OF CONTRACTOR T. Weane,
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
마른 발표를 즐겁고 있다. 마리 발표를 들고 있다.	
	LA Stream
D 4.	2^{2}
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 6485

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio,
Massillon, Ohio, 4/7/57 19
RECEIVED OF FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED / O. L. N. C
아이들은 아이들 그 아이들의 전환 등 그리고 하는 일이 살으면 함께 없다. 중심 중심인
TO TAP SEWER ON THE
OF ROLL TYPE OF STREET COLAND
THE PREMISES BEING LOT NO. 10594 , HOUSE NO. 219
경기에 가는 하는 하는 것이 되는 것이 없는 하는 이 이 등 그는 이 사람들 때문을 모양을 받는 말을 했다.
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
그는 이 이번 회로 말 모든 하는 그 이번 일하를 하는 그는 이 이번 보는 것이를 하는 수 있을 수 없었다.
NAME OF CONTRACTOR OF Duance
要一种大型 (1997年),我们还是我们的人们的最后,我们的身体,我们就是这样的人,我们就是我们的身体,但是这个人,也是不是我们的

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.