N° $_{-}6512$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-/3	-5 C IF SO HOW AND LOCATION FROM	
-HOUSE NO. 5-42		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	28 11 Deel
WAS LATERAL AT CURB? Y	2.5	
WAS ATTACHED TO MAIN	O NAME OF CONTRACTOR	9 Diano
SHOW BY DIAGRAM RELATION (OF LATERAL TO WALL OF BUILDING SERVED.	
		12/
		/ schep
		11/ 28" Dee10
D. D		
SIGNED	FILED AT ENGINEER'S OF	FICE
REMARKS		

Nº 6512

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		SSILLON, OHIO,	, gt	19
RECEIVED OF	Learlas Aun		FEE OF S	
FOR WHICH PERMISSION IS GRAN	ITED A Boundary	1. (29)		
	SEWER	ON THE	J.	
THE PREMISES BEING LOT NO.	AVE. TYPE O ST. TYPE O G 496 East	- 1/2 HOUSE NO	542	
WORK TO BE DONE IN ACCORD				COUNCIL
WORK TO BE DONE IN ACCORD RULES OF THE DEPARTMENT OF	그림에 보고 있는 내가게 들어야는 보다는 생생들이	NO, ESES, BULT FA		COUNCIL,
	Λ			

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.