Nº 6514

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-17-5 (FIRST MANHOLE DOWN STREAM TAPPED 49100
HOUSE NO. 1206	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? /// 0	
WAS ATTACHED TO MAIN 785	NAME OF CONTRACTOR Pay Rember Caril Squer for VA
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
\geq	212 4 1/27 ole
	city pold at. 1/ 3 clee
	Frinst 1,/ Tapped
	Q 1/3/ V5'
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE) IN JULY
REMARKS	
아이들 것 같아요 한 일 하는 것 같아 그렇게 하는 것을 가고 있다면 하다.	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PA RULES OF THE DEPARTMENT OF PUBLIC SERVICE. Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

6514