

Nº 6518

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-25-56

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 921

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

197' 7' Deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

William S. Ringler

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Ray Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

8-21
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 6518

PERMIT TO TAP SEWER

MASSILLON, OHIO, June 23rd 1919

RECEIVED OF Glick Bros. FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED ~~Atch~~ Byron Silt

TO TAP Sanitary SEWER ON THE West

OF Niles Ave AVE. ST. TYPE OF STREET dirt

THE PREMISES BEING LOT NO. 8972 HOUSE NO. 921

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Urban & Ringley

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.