N_{\cdot}^{0} 6539

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2362	The state of the s	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 202	6'D-6
WAS LATERAL AT CURB? V-65		1
WAS ATTACHED TO MAIN//	NAME OF CONTRACTOR (1 X).10	is the
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
		18'
7		lace
	18.7	7
Radi	2021	
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	
REMARKS		

$\mathbf{N}^{\mathbf{0}}$ 6539

PERMIT TO TAP SEWER

MASS	ILLON, OHIO, // 20/36 19
RECEIVED OF	FEE OF \$ 3
FOR WHICH PERMISSION IS GRANTED	1 walker
	THE
OF AVE. TYPE OF ST. TYPE OF S	STREET
THE PREMISES BEING LOT NO.	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	O. 2323. DULY PASSED BY THE CITY COUNCIL

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL.

NAME OF CONTRACTOR CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.