FOLLOWING DATA TO BE ANSWERED BY INSPECTOR **CASE AND SIGNED WHEN RETURNED**

DATE INSPECTED 7-29-56	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO.			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	100'	7'0-00
WAS LATERAL AT CURBY		er de de version de la companya del companya del companya de la co	, particular
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Allaban	XMM.
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SE	RVED.	
and the control of the second of the control of the	A Committee of the Comm		
		3	
ana produce a <u>la calenda de la calenda de</u>	The section of sections and the section of	70	
· · · · · · · · · · · · · · · · · · ·		6	, D 1
_ / / / / / / / / / / / / / / / / / / /	Annual Control of the		
SIGNED P. Lathanni INSPECTOR FOR CITY		GINEER'S OFFICE	
REMARKS			

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE Nº 6559 PERMIT TO TAP SEWER

		Massillon, Ohio,	8/27	19.
RECEIVED OF_	Glick			
	ON IS GRANTED MAN	- ·		
the second secon	nitary.			
OF 14Th	8 + 1 (1) AVE.	TYPE OF STREET	diet	
THE PREMISES BEING	LOT NO. 59314/	94 8931, HOUSE	E NO. 9	//
WORK TO BE DONE II	N ACCORDANCE WITH ORDI	NANCE No. 2323, DUL	Y PASSED BY THE	CITY COUNCIL.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.