

Nº 6562

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

DATE INSPECTED \_\_\_\_\_

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. \_\_\_\_\_

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_


SIZE OF PIPE USED \_\_\_\_\_

WAS LATERAL AT CURB? \_\_\_\_\_

WAS ATTACHED TO MAIN \_\_\_\_\_

NAME OF CONTRACTOR \_\_\_\_\_

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED \_\_\_\_\_

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

# OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6562

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/31/56 1956

RECEIVED OF C. J. Merina FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Friendship Baptist Church

TO TAP San SEWER ON THE West

OF Young Park E AVE. ST. TYPE OF STREET oil

THE PREMISES BEING LOT NO. 01 56 HOUSE NO. 629

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR C. J. Merina

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.