

No. 6568

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-11-56 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____



HOUSE NO. 106

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 24'
CURB LINE AND DEPTH 10' D-e.

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No NAME OF CONTRACTOR P. R. Penley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED P. R. Penley FILED AT ENGINEER'S OFFICE _____
INSPECTOR FOR CITY

REMARKS _____

11-15-56

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6568

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/21 1920RECEIVED OF R. RemyFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Chas. J. RemyTO TAP 18thSEWER ON THE EOF 18th NE

AVE.

ST. TYPE OF STREET HighTHE PREMISES BEING LOT NO. 6310HOUSE NO. 150

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL.
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remy

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.