Nº 6584

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-1-5-C	IF SO HOW AND LOCATION FROM WYE	1241' 11'00
HOUSE NO. 6737		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? NO		
WAS ATTACHED TO MAIN Ves	NAME OF CONTRACTOR	a Denina
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED	
		16
		1 orach.
	en e	58
	/ **	1
		itely
D. U.		
SIGNED /NSPECTOR FOR CIT	FILED AT ENGINEER'S	OFFICE 4 - 2 2 - 5 /
REMARKS		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Nº 6584

			MAS	SILLON, OHIO,	4.5	0/17	'n kin byk a	19:
RECEIVED OF	71 +	1	300	J.	<u></u>		E OF 5	<u>(</u> 20
FOR WHICH PERMISSI	/ ' ON IS GRANTEI	/ :	Mana	e ott			11. 7	7 <u>wa</u>
TO TAP	An m)	•	SEWER OI	N THE	(d).	t Harakan	17 - 17 - 17 - 17 - 17 - 17 - 17 - 17 -	
of Atima	(k)	nu a	VE. T, TYPE OF	STREET	Aira		e tel t	
THE PREMISES BEING		1 .		, Hous				 :
WORK TO BE DONE				lo. 2323, pu	LY PASSED	BY THE	CITY COU	NCIL,
TO LES OF THE BEIN								

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.