Nº 6588

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	:
DATE INSPECTED 11-5-5-6	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO 5~6 /	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	CURB LINE AND DEPTH 70 8 De 7
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	The state of the s
	18'
	- 7dup
The same of the sa	30'
<u> </u>	18' g'cleers
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
/ INSPECTOR FOR CIT	1 - 2 6 - 5 1
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6588

PERMIT TO TAP SEWER

Massillon, Ohio, 10/17	19:
RECEIVED OF 1 4 A BCAR And FEE OF \$2 -	.,
FOR WHICH PERMISSION IS GRANTED	
TO TAP SEWER ON THE	
of Atumber of Street disk	
THE PREMISES BEING LOT NO. 11.41 , HOUSE NO. 541	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC	HL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.