## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 6616 AND SIGNED WHEN RETURNED

DATE INSPECTED 8-9-5-C	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATER	PAL TO WALL OF BUILDING SERVED.
	July 14 March
- 100 (100 年) - 100 (100 日 - 100 日 -	14'
	20
n. 14	started rezmout
SIGNED /INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 6616

## PERMIT TO TAP SEWER

Massillon, Ohio, Massillon, Ohio,	U 19 1880 19
RECEIVED OF Mel Schwarm	,
FOR WHICH PERMISSION IS GRANTED	
TO TAP RACULTARY SEWER ON THE	
of Marid ME AVE. TYPE OF STREET der	•
THE PREMISES BEING LOT NO. 5-/5.5 HOUSE NO.	5
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED E	BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR TRANSLEY	
Note. This permit covers work outside of building only	Any work in

walls of building is subject to Massillon Board of Health Regulations.