Nº 6620

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-4/-<	FIRST MANHOLE DOWN STREAM 13/0/00 MM 5 1)-
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN Ves	NAME OF CONTRACTOR Q Diana
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	20'
and the control of th	2 dup
and the second s	N in the same
	50
	30'
P. J.	
SIGNED / INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 6620 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

MASSILLON, OHIO, MAU, 27	10
MASSILLON, OHIO,	IS.
RECEIVED OF THERMANY RECORDER CO. FEE OF S	OC
FOR WHICH PERMISSION IS GRANTED GREECE CO.	
TO TAP SAW, SEWER ON THE SAWAR	
OF 3rd 15 AVE. TYPE OF STREET 1911	
THE PREMISES BEING LOT NO. 101, 49 HOUSE NO. 739	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COL	INCIL,
Rules of the Department of Public Service.	1.11
Rules of the Department of Tubelo Service.	
NAME OF CONTRACTOR	•
4	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.