

Nº 6642

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-30-57

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 225

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

129'

11' deep

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN no

NAME OF CONTRACTOR _____

F.B. Wilson

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

→ N



SIGNED _____

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

14-47

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6642

PERMIT TO TAP SEWER

MASSILLON, OHIO,

1/26

19

RECEIVED OF

Geo. L. Lott

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER ON THE

W

OF

23rd 7th

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

3714

HOUSE NO.

225

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

L. Lott

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

2-9-57