## Nº 6649

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-23-57	IF SO HOW AND LOCATION FROM TAPPED 138-40
HOUSE NO. 581	
SIZE OF PIPE USED 611	DISTANCE FROM FIRST MANHOLE 19 (*)  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	un en la cultura de la compansión de la co La compansión de la compa
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR TV. Vilan
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	4
	1-1/1/0
kulla kulla tata. Tatan yang berarasa kelang kelang kela <del>ng berarasa kelang ber</del> arasa berarasa berarasa berarasa Berarasa	> N
	17' 4'desp /38
SIGNED Port Lat	herm FILED AT ENGINEER'S OFFICE
/INSPECTOR FOR CI	e de la
· · · · · · · · · · · · · · · · · · ·	

## Nº 6649

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

en e	Massillon, C	оню. <del>1</del>	L23	19
RECEIVED OF 1441	ery Brukan	, .	FEE OF \$	7 <u>0</u>
FOR WHICH PERMISSION IS GRANTI	ED William Col	Greater	ON.	
TO TAP	SEWER ON THE	4100	A min	
or 47.266	AVE. ST. TYPE OF STREET_	MA	2	•
THE PREMISES BEING LOT NO	//278, н	louse no	58/	
WORK TO BE DONE IN ACCORDANGE TO BE DEPARTMENT OF P		, DULY PASSE	D BY THE CITY COUN	ICIL
NAME OF CONTRACTOR HAVE	ry B Webau			

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.