

NO. 6663 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/21/57

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 3' from upstream M.H. 5 1/2' d.

HOUSE NO. 3269

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Harry Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William E. White
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 6663

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/23 1919RECEIVED OF Geo. L. LottFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED SameTO TAP frontSEWER ON THE A.OF Clarendon

AVE.

ST. TYPE OF STREET dirtTHE PREMISES BEING LOT NO. 8589-90HOUSE NO. 3269

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR W. L. Lott

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.