## Nº 6666

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4/1/57	IF SO HOW AND LOCATION FROM 131 920ccp
HOUSE NO	-
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB?	and the second s
WAS ATTACHED TO MAIN 125	- NAME OF CONTRACTOR Harry Unban
SHOW BY DIAGRAM RELATION OF LAT	
32	Speep
and the second of the second o	N
enous e	
entratification in the contraction of the contraction of the contraction of the contraction of the contraction The contraction of the contraction	
	92 Deep
are market management	
The state of the s	×3× /31 / 11-77-07
SIGNED / INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE
	Marking ignored in Archiel in class, program for the
REMARKS	<u>요 </u>

## Nº 6666

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 1 Por 2 19
RECEIVED OF MATERIA BURGALI FEE OF & 25
FOR WHICH PERMISSION IS GRANTED C. 18/1/11/11
TO TAP MALLI. SEWER ON THE MEET
OF 14 ATC 1 & AVE. TYPE OF STREET AUA
THE PREMISES BEING LOT NO. 2257, HOUSE NO. 124
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR HATTIL B. Willaw

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.