

No 6673

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-17-57IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 110SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 106'WAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN NoNAME OF CONTRACTOR H. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N ←

9' - 5' dec.
26'
8' - 6' dec.

SIGNED

Ray Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5-20-57

REMARKS _____

Nº 6673

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, April 17 1919

RECEIVED OF Frank Glick FEE OF \$ 2⁰⁰

FOR WHICH PERMISSION IS GRANTED Frank Glick

TO TAP San SEWER ON THE east

OF 14th S.W. AVE. ST. TYPE OF STREET Street

THE PREMISES BEING LOT NO. 8922, HOUSE NO. 1110

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry B. McKean

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.