## Nº \_6681

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5/1/57	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  FIRST MANHOLE DOWN STREAM	
HOUSE NO. 165 SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	:
WAS LATERAL AT CURBY Yes		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR BEAVER CONST	
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.	
		÷.
7,6==	The state of the s	
$\langle n \rangle$	or the first of the common that the common of the common o	
18.	PROP. LINE	
	FLOW FLOW	
SIGNED William & While	7) 48' ——	
/ INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 5 20 57	
REMARKS		1.

## Nº 6681

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	Krel 30	19.
RECEIVED OF / VAII Sterling	-Benveril	Touch FEE OF 5	2.0
	Demenica		
TO TAPSEW	ER ON THE	earth	
OF 24th 77. W. AVE. TYP			
THE PREMISES BEING LOT NO. 11426	, HOUSE NO		
WORK TO BE DONE IN ACCORDANCE WITH ORDINAL	NCE NO. 2323, DULY P.	ASSED BY THE CITY CO	UNCIL,
Rules of the Department of Public Service.			
NAME OF CONTRACTOR Beaver Car	A.		
NAME OF CONTRACTOR SAME OF CONTRACTOR	<u> </u>		

Note This permit covers work outside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.