Nº _6686

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $5-17-57$	IF SO HOW AND LOCATION FROM 49 9 Defi
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI	
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR a Deang
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
And the second s	
	>N 8deep 1
	\mathcal{H}'
	ر المار الما
•	90et) 151 4c
SIGNED Por Lathan	FILED AT ENGINEER'S OFFICE
/ INSPECTOR FOR CIT	ry and the second secon
REMARKS	

Nº 6686

PERMIT TO TAP SEWER

	MASSILLON, OHIO, 5/2/ 19
RECEIVED OF A. J.	FEE OF 5
FOR WHICH PERMISSION IS GRANTED	a) Hanned
TO TAP Anna Property Se	WER ON THE 11 side
OF 24-2 At 1 61. AVE. TY	YPE OF STREET
THE PREMISES BEING LOT NO. 3177-98	, HOUSE NO. 137
	ANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
NAME OF CONTRACTOR	
	outside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.