Nº 6700

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-7-57	IF SO HOW AND LOCATION FROM 11 11 99 11 Det
HOUSE NO. 31 44	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBY NO	
WAS ATTACHED TO MAIN Y. LS	NAME OF CONTRACTOR Penley
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
\mathcal{N}	
	1 3 deep
	150
	11,000 ac
SIGNED Poy Father INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 6700

PERMIT TO TAP SEWER

The second secon	IASSILLON, OHIO,	
RECEIVED OF Account of	Pen lend	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	in Theat	
TO TAP SEWE	R ON THE	
JO TAP	CON THE)
OF AVE. TYPE	OF STREET	and the second
		/
THE PREMISES BEING LOT NO. 10 20 1	, HOUSE NO,	7/4/4
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC		
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	•	
NAME OF CONTRACTOR Sammer L	Dillon .	
7/		
Note This permit covers work ou	tside of building	only. Any work in

walls of building is subject to Massillon Board of Health Regulations.