

Nº 6702

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-6-57

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 801

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

137' 10' Deep


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

R P Penley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

10-64
8-30-51
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 6702

PERMIT TO TAP SEWER

MASSILLON, OHIO, June 27 1951

RECEIVED OF Raymond Remley FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED Jim Roth

TO TAP San SEWER ON THE South

OF Andy Drive AVE. ST. TYPE OF STREET West

THE PREMISES BEING LOT NO. 11402, HOUSE NO. 1801

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Remley

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.